

Renewal #156

NW cor D.L.C. #49
79

T305 R6W

Found:

14" D Fir wood stump N 72 1/2 E 17°
Scribe Found "BT"

No trace of SW BT.

Also Brass cap NAD for D.L.C. cor
buried & badly bent.

I try to straighten cap but it broke.
Deposit broken cap along side
New Brass cap

Renewal

Set New Brass cap at D.L.C. cor
with steel fence post along side.

county Surveyors office

T305 R6W

NW D.L.C. COR
#49

1969

New Bearing Trees

38" W oak South 171°
scribed NW D.L.C. #49 CS BT

42" W oak N 83 1/2 E 129°
scribed NW D.L.C. #49 CS BT

Note:

This cor lies approx 65°
North & 30' East of small
Pavise

9-11-69

O.K.
J.W.D.

~~J.W.D.~~
~~J.W.D.~~

#203

C.S. File No. 53/40-110