

Fd. OK. 25-J

1/4  $\frac{511}{514}$

see Rev. #13 & Cadastral  
Field Notes for 1957 BA-5  
cap & B.T.S. at fence cor.  
fences N & E.

Fd. S.E. COR. DLC 49 T25S R4W

Reported BRASS cap gone by local  
Resident we Reset from B.T.S.

see Rev. # 101

DIETZGEN NO. 385-2

OK  
5/2/57

LS 53/A7-17