

Renew $\frac{1}{4}$ 511/512 T255 R4W

Ed. at Cor. $1\frac{1}{4}$ " IRON Axle/shaft as
called for in Renewal # 12 & Stump
of ONE BT- NO TRACE of other BT-
24" Now 30" D. Fir Stump N. 70° E 19 $\frac{1}{2}$ ft.

Show SCRA-we open & find Burned face.
we MK. 2 new BTs -

8" R. Cedar N. 1° E. 5 $\frac{6}{8}$ FT.

Mkd " $\frac{1}{4}$ 5 12 CS BT "

7" R Cedar S. 34° W. 37 $\frac{5}{8}$ FT.

Mkd " $\frac{1}{4}$ 5 11 CS BT "

This cor. lies on E. edge of
old cat Road-3 $\frac{0}{8}$ FT N. of Fence cor.

Nov. 20, 1964

V.R.T.
M.D.
J.B.

V.R. Tracy

+ X 86

U.S. File No. 53/47-27