

Renew Sec. Cor.

$\begin{array}{r l} 5 & 4 \\ \hline 8 & 9 \end{array}$	T 92 S R 5 W
--	-----------------

Found:

Original Madrone (now 25)

S 57 W 75 LKS.
SHOWS FACE

Original Fir (now 35")

N 11 W 40 LKS
SHOWS rotted face

The SE tree reported
by the government in
1962 has been cut.

1962 TREES FOUND:

10" FIR N 66 E 11.9
FULL SCRIBING VISIBLE

10" FIR S 12 E 31.0
FULL SCRIBING VISIBLE

14" FIR N 13 1/2 W 70.6
FULL SCRIBING VISIBLE

No trace of SW tree

BRASS CAP lost in
logging operation

(over)

OX*137

C. S. File No.

53/52-59

DIETZGEN NO. 385-6

Set Brass Cap at Cor.

Marked:

County Surveyor's Office

T 32 S

55	54	R
58	59	N

1965

June 25, 1965

B.R.

M.S.

FILED


RECEIVED

JUN 28 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Section 5 Twp 32.S Rge 500 W

Date: JUN 24 45



How was corner identified? _____

Condition of corner: B.S. OUT

BTS OK.

Best route to reach corner: SWR. KNOCKED OUT BY

SEAMIT & CRENSHAW CO.

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing	<u>OLD HAY 99 N BOX 59.</u>			
Condition of Scribe	<u>CELENDARE</u>			
Original or Resurvey				
Appearance of B.T.	<u>CHARGE FOR THIS</u>			
Tags, Marks, etc.	<u>SWR</u>			

James M. Cress
Signed