

Renewal

S18/S17

T.30S R.9W

Found:

30" Fir Stump S66E 2.37

opened stump for examining "S"

8" Hemlock N52W 13.2

No trace of this tree.

Renewed:

Set Brass cap RT $\frac{1}{4}$ cor. N. 1/2

county Surveyors Office

T.30S R.9W

$\frac{1}{4}$ S18S17

1965

New Bearing Trees:

6" Cedar S82E 45.2

Scribed $\frac{1}{4}$ S17 CS RT

13" Douglas Fir N37W 50.2

Scribed $\frac{1}{4}$ S18 CS RT

This cap is located in badly
burnt & brushy area
Spell Ravine about 100' East

11-19-65

J. M. O.

J. C. O.

J. M. O.

C. S. File No. 53/53-17

DIETZGEN NO. 385-G

Q
+ X