

Renewal

1/4 32 T305 R9W

Found:

8" Cedar Now uproot N23W 13°

20" Fir Now burnt stamp 528E 66°
Scribe visible "5"

Also 1" Iron Pipe 4' from on edge of
new road

Set BRASS CAP MKD:

County Surveyors Office

T305 R9W

1/4 5352

1967

New Boring objects:

30" Fir STAMP N34W 29°
Drove Iron Spike in top of stamp

28" Fir STAMP N7E 32°
Drove Iron Spike in top of stamp

Note: This area was recently burned
no trees to scribe;
Also corner lies on west edge of set
road

27 September 1967

Renewal No. 36

G 13
JWJ

96 O.K. J.W.B.

C.S. File No. 53/53-20

DIETZEN NO. 385-S