

Renewal T30S
 R S25 | 530 R
 10 S36 | 531 9
 W W

Found:

15" cedar now 24" N 68 E 20 ⁵/₂
 open found scribing "30"

40" cedar S 20 E 10 ⁹/₂

This tree down & burnt

18" cedar now 26" S 33 W 9 ⁵/₂

This tree shows good scars.

36" cedar now 45" N 65 W 9 ⁹/₂

This tree shows scar

1/4 X 1/4 Stone, had been rolled downhill

Renewed:

Set Brass cap at sec cor. Mt. D.,
 County Surveyors office

T30S
 R S25 | 530 R
 10 S36 | 531 9
 W W
 1965

New Bearing trees

24" Cedar N 68 E 20 ⁵/₂

Scribed T30S R9W S30 CS DT

40" Fir S 50 E 16 ³/₂

Scribed T30S R9W S31 CS DT

11-12-35
 J. C. 33
 1965

#82
 + X

C. S. File No. 53/53-28

DIETZEN NO. 385-6