

Renew $\frac{1}{4}$ 535 / 536 T305 R9W

Ed. at ORIGINAL cedar B.T. -

20" now 21" cedar N. 60° W. 21' ft
open & shows faint "1" & "B" scribe.

Other BT is gone, there is a hole

at Bearing & approx. distance from
the corner point to where it should
have been. Set for Cor. 1" I.P.

& Brass Cap, MKd. "COUNTY SURVEYOR'S
OFFICE 1964 T305 R9W $\frac{1}{4}$ 535/536

& MKd. New BT's -

8" W. FIR S. 14° W. 8 $\frac{3}{4}$ ft.

Mkd. $\frac{1}{4}$ 535 CS BT"

13" W. FIR S. 41° E. 6 $\frac{9}{16}$ ft.

Mkd. $\frac{1}{4}$ 536 CS BT"

Oct 5, 1964

V.R.T.
M.D.

V.R. Tracy