

$\frac{1}{4}$ S $\frac{9}{16}$ T305 R9W Renewal #4

Fd. at $\frac{1}{4}$ CORNER Both ORIGINAL B.T.'s,
2 white oak (Now SNAZ) 16" dia.
S. 27° E. 19 $\frac{3}{8}$ ft. - No scribe
left on Rotted face.

2 D. FIR (Alive but Buried) 21"
dia. (called for 24" orig.) N. 40W.
13 $\frac{3}{4}$ ft.

Eppstein's 1931 B.T.'s Both down
and Rotting - No sign of Rock
called.

Set 1" I.P. & BRASS Cap FOR COR MKD.

"County Surveyors Office 1964

T305 R9W $\frac{1}{4}$ S $\frac{9}{16}$

MKD New B.T.'s:

14" B. OAK S. 21° E. 35 $\frac{0}{8}$ ft.

MKD $\frac{1}{4}$ S 16 CS BT

11" D. FIR N. 51° E. 28 $\frac{3}{4}$ ft.

MKD $\frac{1}{4}$ S 9 CS BT

V.R.T.

M. D.

~~E. R. Tracy~~ July 31, 1964

M. D.

OX ✓

C. S. File No.

53/53-53