

Renewal  $\frac{33}{2} | \frac{34}{3}$  T305 T315 P9W

Found:

17" D Fir now 38" N63 $\frac{3}{4}$ E 22 (Rec 25 $\frac{1}{2}$ )  
 Shows good scar

7" D Fir now 26" S31 $\frac{1}{2}$ E 38 $\frac{1}{2}$   
 Shows good scar

6" D Fir now 19" N89 $\frac{1}{2}$ W 16 $\frac{1}{2}$   
 opened for scribe "W"

20" Cedar now 57 $\frac{1}{2}$ " S32 $\frac{1}{2}$ W 19 $\frac{1}{2}$   
 (Rec 49 $\frac{1}{2}$ " 16 $\frac{1}{2}$ )  
 Burnt Face on Tree also "X"

Renewal:

Set Brass cap at Sen Con 1970  
 county Surveyors office

~~XXXXXXXXXX~~  
 $\frac{533}{54} | \frac{589}{53}$   
 T313  
 1970

New Bearing Tree.

15" D. Fir S60 $\frac{1}{2}$ W 32 $\frac{1}{2}$   
 Scribed T315 P9W S4 US BT

Other BT's OK.

Note this con lies in bottom of  
 the draw.

OK.  
 J. W. H.

8-11-70  
~~J. W. H.~~

999-1309  
 =192-72

C. S. File No. 53/53 59

DIETZGEN NO. 385-6