

Renew Sec. Cor. $\frac{8}{17} \frac{9}{16}$ T305 R9W

Ed at cor 3 original BTs & Rock mound
called for, cor stone gone.

12" Now 14" Oak N. $66\frac{3}{4}^{\circ}$ W. 63 $\frac{1}{2}$ Ft.

Shows good scar.

30" Now 40" Fir S. 50° W. 76 $\frac{1}{2}$ Ft.
Shows good scar. Now stop. Don't find 30"

24" Now 36" Fir S. $17\frac{1}{2}^{\circ}$ E. 123 $\frac{1}{2}$ Ft.

Shows good scar. 2nd cor. location

We set 1" I.P. & Brass cap in mound
of stone & mk. "COUNTY SURVEYORS

OFFICE 1964 T305 R9W $\frac{58}{517} \frac{59}{516}$ "

& mk. New BTs -

14" W. Oak N. 22° E. 21 $\frac{1}{2}$ Ft.

Mkd "T305 R9W 59 CS BT."

12" Laurel N. 61° W. 19 $\frac{1}{2}$ Ft.

Mkd. "T305 R9W 58 CS BT."

9" W. Oak S. 33° W. 49 $\frac{1}{2}$ Ft.

Mkd. "T305 R9W 517 CS BT"

10" W. Oak S. 42° E. 53 $\frac{1}{2}$ Ft.

Mkd. "T305 R9W 516 CS BT."

Oct, 13, 1964

V.R.T.
M.D.
J.B.

~~V.R.T. [Signature]~~

+ X

C. S. File No. 53/8-69