

512/51
Renew Sec. COR. 513/518 T305 R's 9 & 10 W.

Ed. 3rd COR. Rock 12" x 10" x 10" with 4
notches on S. Edge No Edge Broken off.

Ed. 3 BTs as recorded in survey of 1893.

36" cedar (stump) N. 46° E. 27⁴/₄ ft

Shows original "R BT" scribe & new
scribe "57 183 BT"

30" cedar (stump) S. 63¹/₂° W. 28¹/₄ ft

We do not open

26" cedar (Face down & Rotten) N. 56¹/₂° W. 24⁴/₄ ft.

3rd COR pt. We set 1" I.P. & BRASS Cap MKd.

"DOUG. CO. SURVEYOR'S OFFICE 1964

T305 R9W R10W 512/517
513/518 1st mound

of stone & MK New BT's -

7" Myrtle N. 65° E 7⁰ ft.

Mkd. "57 DCS BT"

16" Alder S. 4° E. 38⁶/₄ ft.

Mkd. "T305 R9W 518 DCS BT"

6" Maple S. 16° W. 22³/₄ ft.

Mkd. "T305 R10W 513 DCS BT"

15" Alder N. 33° W. 36⁸/₄ ft.

Mkd. T305 R10W 512 DCS BT"

This COR. Lies on E. Bank of creek

approx. 3⁰ ft above creek.

IRT.

M.D.

T.B.

Oct. 26, 1964

#13
+X

911A Trace

C.S. File No. 53/53-73