


Section 23

Twp 30S

Rge 9

W

Date: May 21, 1965



How was corner identified? Bearing trees present

Condition of corner: Evidently destroyed by

(North $\frac{1}{4}$ Cor.) cat logging.

Best route to reach corner: _____

Quadrant	NE	NW	SE	SW
Species & Size	Find I.P. & B.T's 25			
Dist. & Bearing	Renewal # 20			
Condition of Scribe	ARJ			
Original or Resurvey	5/27/65			
Appearance of B.T.				
Tags, Marks, etc.				

Recorded
Other Remarks: V.R.T.
M.D.

Signed
Don Burkhardt

C.S. File No. 53653-46