

Renewal #6

9/10
16/15

T205 R11W

Found:

8" Hemlock NW Corner stump S 62 W 99
found Reverse scribe "W"

3 other BTs Markers not found

Also 2" Iron Pipe set by gate not found as car falls in deep cut of skid rd.

Renewal

Set Brass cap at Sec cor MND
County Surveyors office

T205 R11W

59 / S10
S16 / S15
1969

New Bearing Trees

4" Hemlock S 29 W 19 1/2
scribed S16 CS BT

4" Hemlock N 76 E 13 0
scribed S10 CS BT

4" Hemlock N 53 W 9 1/2
scribed S9 CS BT

NO Other Trees In Area

Note:

This cor lies approx 50' north of
ridge & 250' south of draw
Running E-W, This cor lies also in
old skid rd running N-S

9-25-69

J. J. J.

#70

D. V. J. J.

C. S. File No. 53/66-12