

Renewal

20/21

T203 P12W

Found

1 1/2" I.P.R. at corner Badly Rusted
See C.S. 52/91

36" Spruce (New D.F. stump) S73W 52
Previously open scribble found part of
"5"

24" Spruce (New 4' stub) N10E 11E
PS Noted 2.8 70 dont spike in
root of tree, set 1993 by W.G. Corbett

Call of / chain, north to top
of ridge, hits good,

Renewal

Set Brass cap at corner along side
I.P.R. 1949
County Surveyors office

T203 P12W

1/4
S20 S21

1971

New Bearing Trees

6" D.F. 587E 30E
Scribbled 1/4 S 21 CS BT

16" Spruce S 58 W
Scribbled 1/4 S 20 CS BT

Also Found:

1 1/2" I.P.R. N52E 39E
Note

Best way to reach cor - good walk
Run south from crown 20 ft back gate

6-16-71

SEE 52/91
CS

D.K.
J.W.B.

CS 53/66-32

#44