

Renewal

17/16
20/21

T20S R12W

Found

1 1/2" T.P.P. Badly Busted at sec. cap
SPEC. S. 52/91

orig.

18" Fir near 22" stub S 67E 96²

scribe visible T20S R12W S21 -

opened BT scar for scribe "BT"

Very old scribing.

-1993-

5' Spruce stump S 22 E 39²

To R.P. Spike

No trace of other nails set or
orig. BTs

Possible orig -

Fir stump N 63 W S 1² (Rec 98²)

Renewal

Set Brass cap along side T.P.P. near
county surveyors office

T20S

S 17 1/2 E
S 20 1/2 E

R12W
1971

Next Bearing Tree

7" Fir S 31 W 105²
scribed T20S R12W S20 CS BT

No other trees available

SEE CS 52/91
O.M. J.W.B.

~~4/5~~

C.S. File No. 53/66-33