

Renew $\frac{1}{4}$ 532 | 533 T195 R10W
Fd. ORIG. COR. STONE 24" X 15" X 10" MKD
" $\frac{1}{4}$ " Tipped over. & O.B.T. as follows
ORIG. 14" Now 26" F, R S. 45° E, 9 $\frac{1}{2}$ ft,
2 live - shows good SCAR - We Rescribe
" $\frac{1}{4}$ 533 CS BT" No Trace other
O.B.T. - at COR. Point in hole
where stone Tipped out of - set
1" I.P. & BRASS CAP MKD: "COUNTY
SURVEYOR'S OFFICE 1969
T195 $\frac{1}{4}$ 533 | 532 R10W" & MK.

New B.T. -
28" DF; R S, 41° W, 7 $\frac{3}{4}$ ft,
MKD. " $\frac{1}{4}$ 532 CS BT"

This COR. Lies on steep S.E.
Slope in very Dense BRUSH,
Note, see over.

June 26, 1969

V.R.T.
J.G.H.
V.D.R.

V.R. Tracy

O.K.
J.W.B.

#11
0

C. S. File No. 53166-37

cont.
FROM OTHER SIDE -

ON OUR 1ST. SEARCH FOR
THIS COR. WE FOUND A FALSE
N.S. BLAZED LINE APPROX
100 FT. E. OF TRU. LINE.

U.R.T