

REN. TWPS 20 & 21 S R11 W 1/4 S35
S2

AT COR. FD. 3/4" IRON PIPE.

FD. RED CEDAR (NOW 52" DIAM.)

S 10° W 12° FT. - PREVIOUSLY OPENED
THROUGH ROTTEN WOOD ON SOUTH SIDE -
GOOD REVERSE SCRIBING VISIBLE ON
OVERGROWTH OF OLD FACE. " 1/4 "

FD. FIR STUMP S 82° W 11 1/2 FT. -
CUT OFF BELOW MARKINGS.

EPP'S OTHER BT. DESTROYED BY
ROAD CONSTRUCTION.

BLAZE & SCRIBE 2 TREES:

23" RED CEDAR N 58° E 34 1/2 FT.

MKD. " 1/4 S 35 CS BT "

52" RED CEDAR S 10° W 12° FT.

MKD. " 1/4 S 2 CS BT " - (ORIG. B.T.)

CORNER IS ON ^{TOP} EDGE OF CUT
BANK ON E. SIDE OF SMITH RIVER
ROAD

SEE REN. #2

T 20 S R 11 W

SEPT. 18, 1964

M.G.

W.S.

M.S.

Milo E. Godfrey

~~00~~
~~+~~