

T195

Review Closing Cor 55/54 T205 R9W

Fd. 1921 G.L.O. BRASS Buried under
48" cedar Log. - Badly Rusted pipe &
STUMPS of O.B.T.s as follows -

14" Now 20" Maple S. 38° E. 17 ⁸/₁₆ ft.

Now shattered STAMP - No scribe fd on
unhealed Blaze.

30"? Now 24" Alder S. 15° W. 40 ³/₁₆ ft.

Now STAMP - Blaze decayed - No scribe.

at COR. point in place of old COR. pipe
set 1" I.P. & BRASS cap MKd. "COUNTY

SURVEYORS OFFICE 1968 T195

C.F. ⁵³³/_{55/54} R9W T205 " & Deposit old

COR. material along side. MK. new BT.

30" Maple N. 12° W. 67 ⁵/₁₆ ft.

Mkd. "CC 54 55 CS BT" No other

Trees available. This COR. lies

20 ft. E. of small Ravine course

N.E. of 200 ft. S. of middle fork

of Smith River.

July 17, 1968

V.R.T.
J.H.
V.P.

V.R. Tracy

#8-28-9
#3 H-9

D.K. J.W.B.

G.S.M.N.

53/66 - 17