

Renew Closing Cor R10W  $\frac{56}{57}$  T205 R9W

Fd concrete Filled I.P. - no BRASS  
cap - Broken off & a.B.T.'s 25 Follows  
30" Now 34" cedar N. 37° E. 34 3/4 ft,  
alive - shows good SCAR - we Rescribe  
"T205 R9W 56 CC CS BT"

40" Now 42" cedar S 82 1/2° E, 61 1/4 ft,  
Now sowed STUMP - scribe visible on  
unhealed Blaze. No other TREES  
To SE, & No suitable TREES  
close NE, or W. COR, pipe  
was under Logging debris which  
we Remove & set 1" I.P. & BRASS  
cap MKd. "COUNTY SURVEYOR'S OFFICE

1968 T205 R9W  $\frac{56}{57}$  R10W "deposit  
old cor. pipe along side BRASS CAP  
This cor lies approx. 600 ft  
West of Ridge course N. & S. and  
on N. side of Ravine 15 ft. in  
Logged off unit.

July 10, 1968

U. R. T.  
J. H.  
V. P.

*N. R. Tracy*

#10-T20-90  
#31-T20-18 J. W. B.

C. S. File No. 53/66-68