

Review E. $\frac{1}{4}$ 511 T205 R10W

Fd. 1" I.P. Filled with cement at
COR. point with BRASS CAP ¹⁴⁵¹ BROKEN OFF
& gone with B.T.s as follows -

ORIG. 36" NOW 40" F. R. S. 66" W. 16⁵ FT.

2 live shows good SCAR - we do not open

1951 B.T. 6" Yew S. 86 $\frac{1}{2}$ " W. 38⁹ FT.

2 live - " $\frac{1}{4}$ 511 B.T." scribe visible on

partially healed Blaze. Set 1" I.P.

& BRASS CAP IN PLACE OF OLD I.P. MKD.

"COUNTY SURVEYORS OFFICE

1968 T205 R10W $\frac{1}{4}$ 511 R9W" & Deposit

old pipe along side BRASS CAP.

This COR. lies on very steep

N. Slope approx. 50 ft S. of

small creek course N.W.

April 11, 1968

V.R.T.

J.H.

V.P.

V.R.T. Tracy

O.K. J.W.B.

629
27-720-9

CS FILE NO. 53/66-79