

57/58

Review Sec. Cor. 518/517 T205 R10W

Fd. Hain's "T" IRON 25 called for in

Rev. # 18 set at cor from only one

orig BT 25 follows -

5" Fir S40°W 50<sup>2</sup> ft.

Now Badly decayed stump with "W BT"

scribe - unrecorded B.T.s 25 follows -

20" D. Fir (snag) S. 35°W. 54<sup>0</sup> ft.

BARK scribed "T20 R10W 517"

23" D. Fir (snag) S. 73°W. 46<sup>3</sup> ft.

BARKS scribed "BT 57 T205 R10W"

at cor. point set 1" I.P. & BRASS

cap MKd. "COUNTY SURVEYORS OFFICE

1968 T205 <sup>57/58</sup>/<sub>518/517</sub> R10W" Reset

"T" IRON 2 along side BRASS cap & MK.

New B.T.s -

26" Maple N. 81°E. 7<sup>0</sup> ft.

Mkd. "T205 R10W 58 CS BT"

24" Maple S. 22°E. 57<sup>2</sup> ft.

Mkd. "T205 R10W 517 CS BT"

No other suitable trees available

This cor. lies on steep Easterly

slope approx. 50 ft. W. of small

Ravine.

March 28 1968

#19

A. R. T. Rand

U.R.T.

J.H.

C.S. File No. 53/66-85

517  
518  
519  
520  
521  
522  
523  
524  
525  
526  
527  
528  
529  
530  
531  
532  
533  
534  
535  
536  
537  
538  
539  
540  
541  
542  
543  
544  
545  
546  
547  
548  
549  
550