

Renew E.  $\frac{1}{4}$  512 of T20S R12W  
Fd. old 1" Bolt badly Rusted &  
B.T.s by R. Lecklider - see Ren #6  
38" Now 40" Fir N. 72° W. 65  $\frac{3}{4}$  ft  
alive - Lower blaze healed - upper  
blaze nearly healed -  
6" Now 12" Hemlock South 69  $\frac{1}{4}$  ft.  
alive - blazes healed - we set  
1" I.P. & Brass cap MKD. COUNTY  
SURVEYORS OFFICE 1970  
T20S R12W  $\frac{1}{4}$  512 | R11W" in  
place of old Bolt & Reset  
bolt alongside - This cor.  
lies 20 ft. N. of creek  
bottom approx 350 ft. E.  
of very old, unusable log  
Road - Fd. only badly decayed  
Remains of stump of orig. B.T.

March 30, 1970

VRT  
JGN  
VDP

V.R. Tracy

#41-T20-12  
#91-T20-11

O.K.  
C.S. File No. 53/66-91