

T205 R11W

N.F. 3 -

$\frac{1}{4}$  53 & 52 we find No TRACE  
O.B.T.S -

0.5  
1.5  
2.5

C. COR  $\frac{51}{512}$  NO TRACE OF O.B.T.S  
Probably Destroyed  
by Road

M.C. BETWEEN 512 & 56 ON  
N. BANK OF LAKE ONLY SWAMP  
& BRUSH NO TREES AT ALL

N.F.  $\frac{1}{4}$   $\frac{59}{516}$  Logged many years ago  
No O.B.T.S Fd.

N.F.  
SEC. COR  $\frac{52}{511} | \frac{51}{512}$  We find No O.B.T.S  
Trees used were NOT  
To good -

N.F.  
 $\frac{1}{4}$  51 & T205 R12W - Logged many  
years ago - NO O.B.T.S Fd. - VERY  
BRUSHY

N.F.  
M.C. ON S. SIDE OF LAKE BET SEC'S  
7 OF T205 R11W & 512 OF T205 R12W  
NO O.B.T.S - old Log Road probably destroyed  
COR. CS 53/64 - 109