

Renewal

31/32  
5

T215 R9W  
T225 R9W

Found

8" Fir? N17 1/2 E 103'  
This tree opened years ago &  
rotten

I do not find NW BT-

I do find

30" Fir 573 E 128'  
This tree destroyed in 1894.

Using these 2 trees call out

Top of ridge at 42'

And coming 207' East from  
closing cor. of 6/5 I Renew.

Set Brass cap at sec. cor NW/4  
County Surveyors office

T215 R9W

531 | 532  
55

T225  
1971

New Bearing Trees:

22" D. Fir N 83 E 22'  
Scribed T215 R9W 532 cor BT

22" D. Fir N 13 W 24'  
Scribed T215 R9W 531 cor BT

10" D. Fir S 21 E 15'  
Scribed S5 cor BT

9  
#14 T21-9  
#69 T22-9  
#20

O.K.  
J.W.B.

9-29-71  
J.W.B.  
J.H.

C. S. File No. 53/66-126

DIETZGEN NO. 385-6