

Renewal

31
6/5
C.C.

T225 R9W

Found

Splintered stump
Scribed found

N17 W
BT

92⁺

Possible BT Rotten & down

S 27 1/2 W

59⁺

I did not find SE BT.

Call on creek (Draw) of
313⁵ from 31/32 or 106 from 31/5

Hits good

Renewal

Set Brass cap at C.C. MHP.
County Surveyors office

T215 R9W

531
56 | 55
C.C.
T225

1971

New Bearing Trees:

18" D. Fir S 61 W 10⁺
Scribed T225 R9W S 6 46 45 BT

10" D. Fir S 26 E 17⁺
Scribed T225 R9W S 5 46 45 BT

9-29-71

O.K.
J.W.B.

J.W.B.
M.B.B.

C.S. File No. 53/66

DIETZEN NO. 385-6

#15 T21-9
#70 T22-9