

Renew Sec. Cor R9W  $\frac{525}{536} | \frac{530}{531}$  R8W T30S

Fd. O.B.T.s as follows -

orig. 15" now 28" Fir N. 47° W. 24  $\frac{1}{2}$  ft.

alive - open & scribe visible.

orig. 30" now 54" Fir S. 1  $\frac{1}{2}$ ° W. 35  $\frac{1}{2}$  ft.

alive - open & scribe visible.

orig. 15" now 30" pine N. 25° E. 57  $\frac{1}{2}$  ft.

alive - open & scribe visible

we do not find S.E. B.T. -

2<sup>d</sup> cor. point set 1" I.P. & Brass

cap MKd. "COUNTY SURVEYOR'S

OFFICE 1768 T30S R9W  $\frac{525}{536} | \frac{530}{531}$  R9W"

& MK. New B.T.s -

9" D. Fir S. 52° E. 16  $\frac{2}{3}$  ft.

Mkd. "T30S R8W 531 CS BT"

11" White Oak N. 65° E. 34  $\frac{2}{3}$  ft.

Mkd. "T30S R8W 530 CS BT"

8" White Oak N. 10° W. 30  $\frac{1}{2}$  ft.

Mkd. "T30S R9W 525 CS BT"

8" D. Fir S. 82° W. 26  $\frac{1}{2}$  ft.

Mkd. "T30S R9W 536 CS BT"

This cor. lies on steep S.W. slope

August 15, 1968

V.P.T.  
J.H.  
V.P.

\*97-730-9

\*89-308 Tracy

C.S. File No. 53/67-1 J.W.W.B.