

Renew Sec. Cor. ^{18 1/2} 1920 T305 R8W

Fd. one Live BT & Three BT's Down

Dead & Badly Rotted as Follows -

ORIG. 10" OAK N. 74° E. 20[±] ft.

No scribe found - Down out of position.

ORIG. 12" Now 22" Lard S. 11° E. 38[±] ft.

alive - open & find "O T" scribe.

ORIG. 12" Now 16" Lard S. 44° W. 38[±] ft.

Down - open & find old face & fragmentary

Reverse scribe.

orig 15" OAK N. 10° W. 42[±] ft.

Down - Badly Rotted - out of position - No scribe.

Set 1" I.P. & Brass Cap MKd. "COUNTY

SURVEYOR'S OFFICE 1965 T305 ^{518/517} 519/520

R8W" & MK. New BT's -

15" W FIR N. 59° W. 9[±] ft.

Mkd. "T305 R8W 518 CS BT"

20" cedar N. 11° E. 31[±] ft.

Mkd. "T305 R8W 517 CS BT"

15" W. FIR S. 1° E. 19[±] ft.

Mkd. "T305 R8W 520 CS BT"

9" D. FIR S. 31° W. 23[±] ft.

Mkd. "T305 R8W 519 CS BT"

July 16, 1965

V.R.T.
M.D.
T.C.

#70
+X
R. Gray

C. S. File No.

5367-6