

Renew $\frac{1}{4}$ $\frac{522}{527}$ T305 R8W

Fd. 2^d Cor. BRASS Cap f BTs 25

Recorded in Ren. # 16 of 1958,

ORIGINAL BT chopped open and
appears to be starting to Rot.

We MARK New BT in Sec. 22.

18" D. FIR N. 3 ° W. 34²ft.

Mkd. $\frac{1}{4}$ 5 22 CS BT

Sept. 17, 1964

URT.
M.D.
J.B.

~~URT~~

+ X/

C. S. File No. 53/68-34