

56 | 55
Renew Sec. Cor. 57 | 58 T305 R8W

Fd. Remnants of 3 original BT's

at Cor. as follows -

15" Now 24" chinquapin N. 55° E. 4° ft.

Now Badly Rotted Stump - No scribe fd.

14" Now 24" Fir S. 56° E. 5³ ft.

Now SNAG - shows "T3 R W 58 BT"

BARK scribe in poor condition.

15" Now 24" Fir S. 44° W 47⁵ ft.

Turned out - we opened - no scribe

fd. NO TRACE OTHER B.T. - we

Set 1" I.P. & BRASS CAP MKd. COUNTY

SURVEYOR'S OFFICE 1965

T305 R8W $\frac{56}{57} | \frac{55}{58}$ " & MK. New BT's

16" cedar N. 51° W. 28⁴ ft.

Mkd. "T305 R8W 56 CS BT"

5" D. Fir S. 82° W. 5⁸ ft.

Mkd. "57 CS BT"

8" W. Fir S. 18° E. 12⁹ ft.

Mkd. "T305 R8W 58 CS BT"

5" chinquapin N. 53° E. 8⁴ ft.

Mkd. "55 CS BT"

COR. is approx 40° ft south of old
Log Road on top of Ridge.

April 26, 1965

W. J. RAY

V. R. T.
M. D.
J. B.

C. S. File No.

53/67⁴⁰