

Renew $\frac{1}{4}$ S 14 / S 13 T305 R8W

fd. $\frac{3}{4}$ " I.P. & one original BT.

18" Now 40" cedar (down) N. 30° W. 112 ft.

Previously opened & face Burned - we

open lower & find "BT" scribe.

Other BT gone, we find stump hole at

correct bearing & distance. $\frac{3}{4}$ " I.P. fd. is

not recorded. We set 1" I.P. & BRASS

C2p MKd. "COUNTY SURVEYOR'S OFFICE.

1965 T305 R8W $\frac{1}{4}$ S 14 / S 13 " a

M.K. New BTs -

6" W FIR N. 45° E. 100[±] ft.

Mkd. " $\frac{1}{4}$ S 13 CS BT"

9" Pine N 71 $\frac{1}{2}$ ° W. 181[±] ft.

Mkd. " $\frac{1}{4}$ S 14 CS BT"

This cor. lies in logged area

approx 300± ft. N. of Edge of

Timber course E. & W.

April 1, 1965

U.R.T.

M.P.

J.B.

V 552
+ X

C. S. File No.

53/67-49