

Renew Sec. Cor. BR
 T22S R6W | T22S R5W WS
 36 | 31 MS

Found:

20" Fir (now stump) N56 1/2 W
 156' scribing visible

GLO Brass Cap At Cor.
 Marked

CC

T22S R6W
 S36 | S31

T23S R6W
 S1
 1943

Cor is 2' south of E-W FC.

New Bearing Trees:

7" D. Fir N4W 26°
 Marked CCT22S R6W
 S36 CS BT

6" Madrone N62E 22.5
 Marked CC T22S R5W
 S31 CS BT

Feb 3, 1965

G.S. File No. 53/101 24

*75-323
 +80
 *705 *51-23-6