

Renew Sec. Cor

T235
R6W
S1

T235
R5W
S6

Found:

9" Fir (mow stump)
S29E 68.9

No trace of SW Tree

GLO Brass Cap At Cor.

Marked -

T235
R6W
S1

T235
R5W
S6

SC
1943

New Bearing Trees

14" W. Fir S84E 93°

Marked

T235 R5W S6 CSBT

7" D Fir S70W 34°

Marked

T235 R6W S1 CSBT

Cor. is at East-West-South
Fence Corner

Feb 3, 1965 File No. 53/10/1
BR WS MS

106-22-5
50-23-6