

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
3" Fir	N 52 E	40.4	--	X	X	--
6" Fir	S 80 E	25.0	--	X	X	--
28" Fir Stump	S 32 W	49.5	X	X	X	--
14" White Oak	N 12 W	15.6	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Poison Oak, Oregon Grape

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 50 W ON MINUS (-) 20 %

NORTH: - 17% 135' Cr CNW Logged

SOUTH: + 18% "

EAST: + 19% 170' Cr CNW "

WEST: - 19% 4' N-S Fence "

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Glenn McClary DATE: November 11, 1959
~~ENGINEER - SURVEYOR~~

ASSISTED BY: Robert Barta

COPIES SENT TO:

UNDER THE SUPERVISION OF:


SEAL PAGE 3

PUBLIC LAND CORNERS

SPRINGFIELD
FILE
Weyerhaeuser
Springfield
Branch

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22S RANGE 4W
SECTION 33 CORNER SW
COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1851
CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

No trace

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
16" Fir	N 54 E	18	11.9	24" Blowdown stump - badly burned.
40" Fir	S 20 E	46	30.4	large badly burned, rotted Fir stump
16" Fir	S 30 W	78	51.5	28" Fir stump - old axe marks
18" Fir	N 10 W	77	50.8	32" Fir stump - chopped out lower face and found scribed "BT"

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: Set 1" aluminum pipe by distance from NW and MAG. DECL.: 20°

SW original BT's

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
N 38 E	12.8	GLO	Stump out of place
S 18 E	26.5	"	Large burned and rotted fir stump
S 32 W	51.5	"	28" fir stump
N 11 W	50.8	"	32" fir stump

PAGE 1

CS S3/105-25