


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 2 W
SECTION 5 CORNER W 1/4
COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1894

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
6" Vine Maple	N 28° W	13	8.6	Not found.
16" Hemlock	N 12° E	24	15.8	Now 26" Hem. - Chopped out and found scribing.

SURVEY RECORD
DATE: _____

PRESENT CONDITION: _____

CORNER SET: Set Hemlock post for Corner Post is against MAG. DECL.: 20°

a fir log.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 12° E	15.8	GLO	Measured to Face.

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
48" Fir	S 56° E	34.6	--	X	X	--
50" Fir	S 32° W	104.4	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: O.G.F., Hemlock & Cedar

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) West ON MINUS (-) 86 %

NORTH: + 22% for 200'

SOUTH: Level for 70' to Creek - Course NW

EAST: + 80% for 130'

WEST: - 86% for 65' to Creek - Course NW

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: C.G. # 28

BY: W. W. Dixon DATE: Mar. 3, 1961

ENGINEER - SURVEYOR

ASSISTED BY: W. W. Dixon

J. Greer

UNDER THE SUPERVISION OF:

COPIES SENT TO:

SEAL

PAGE 3

CS 53/110-1