

PUBLIC LAND CORNERS


SPRINGFIELD
SURVEY FILE

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 24 S RANGE 3 W

SECTION 2 CORNER SW

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20° E

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
54" Fir Stump	N 68 E	13.9	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Logged East & North; & 30' West.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) ON MINUS (-) %

NORTH: _____

SOUTH: About 50' Enter Timber

EAST: _____

WEST: 30' Enter Timber

FROM CORNER |

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK: _____

BY: M. D. Hale DATE: April 19, 1963

ENGINEER - SURVEYOR

ASSISTED BY: H. E. Case

UNDER THE SUPERVISION OF:

COPIES SENT TO: _____

SEAL

PAGE 3

GLO SURVEY RECORD

DATE: 1871

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
8" Maple	N 85 E	22	14.5	Gone
6" Maple	S 20 E	25	16.5	"
8" Maple	S 32 W	11	7.3	"
8" Maple	N 5 W	29	19.1	"

Weyerhaeuser Co. SURVEY RECORD
DATE: 1958

PRESENT CONDITION:

54" Fir - N 68 E - 13.9 - W/Nail & plate	Now Stump; Added a plate.
60" Fir - N 13 W - 14.1 - W/Nail & plate	Now a stump(1958 error. Distance should be 15.1. Changed plate to 15.1. Distance. Now a stump.
27" Fir - S 17 E - 38.6 - "/ " "	Now a stump.
48" Fir - S 17 W - 49.7 - "/ " "	Now a wind fall.

CORNER SET: 1"X30" Aluminum Pipe - 1963 MAG. DECL.: 20° E

1" X 6" Marker Pipe

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS 53/111-3