

Doug Co Survey

FORM 771 1/69

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY

SPRINGFIELD BRANCH

TOWNSHIP 25 S

RANGE 2 W

SECTION 14

CORNER N E

COUNTY Douglas

OREGON

Condition of Corner as was previously referenced by Weyerhaeuser Company Survey Record 1/30/58:

of 10-12-70. Corner by Glen McChesney 1/30/58.

GL0 - 6/30/1900
Stone - Found

Present Condition 10/12/70
In position - also found 1962 BLM
Brass cap -

38" Fir N 25 E 41 lbs - 27.1'
" Green-face not chopped out 40" fir
N 21 E - 27.1"

Now @ 38" Fir stump
N 21 E - 27.1'

44" Fir S 23 E 15 lbs. 9.9'
" 50" Fir, face not chopped
S 24 E - 9.9"

50" Fir - face overgrown
S 24 E - 9.9'

14" Fir S 55 W 31 lbs. 20.5'
" 25" Fir snag - scribing visible
S 57 W 19.9"

Down -

14" Hemlock N 76 W 26 lbs. 17.2'
" 18" Hemlock - scribing visible
N 73 W - 17.4"

18" Hemlock - scribing visible.
N 73 W - 17.4'

References - plates & "W" Nails:

38" Fir N 21 E 26.0' orig BT

38" Fir stump in place - plate & "W" nail.

(page 1 of 2)

CORNER:

NE Section 14-25S-2W

50" Fir S25E 9.4 orig. BT

38" Cedar S76W 22.0 -

44" Fir stump N33W 18.0 -

50" Fir in place - plate & "W" nail -

Windthrower - "

In place "

Accessories Added 10/12/70:

Drove 1" x 48" monel pipe along north side of stone. Added one new reference with plate & "W" nail on:

8" Hemlock S88 1/2 W 38.7'

Work Done For W. Co

By: L. Wilson Date 10-12-70

Leon Warren

Reported by: Glen McChesney