

Renew E. $\frac{1}{4}$ S10 | T21S R10W

Fd. 1" I.P. filled with concrete badly
Rusted & BRASS cap broken off, also
O.B.T. -

orig. 36" Now 46" FIR N, 38°W, 15⁸ ft.
alive - shows good scar - we cannot
open. S.W. B.T. gone - we find hole
where it would have been - 2^d cor.
point set 1" I.P. & BRASS cap MKd.

"COUNTY SURVEYORS OFFICE 1968
T21S $\frac{1}{4}$ S10 | R10W" & MK. New B.T.S.

9" cedar N, 68°W. 13¹ ft.

Mkd. " $\frac{1}{4}$ S10 CS BT"

12" Hemlock N, 6°W, 26^e ft.

Mkd. " $\frac{1}{4}$ S10 CS BT"

Deposit old pipe & BRASS cap along
side New Monument. This cor.
Lies approx 70 ft South of Top
of SPUR Ridge course west.

9 March 13, 1968

VAT
J.H.
V.P.

(Signature)
V. R. Gray

#5 P.W. J.W.B.

C.S. File No. 94/1-13