

Renew Sec Cor. 521 | 522 T215 R10W

Find 1919 G.L.O. BRASS CAP properly  
MKd & firmly set - Pipe Badly Rusted  
& O.B.T.s 25 follows -

10" now 12" FIR N, 30° E 10 ± ft.  
(Record - N. 20° E.) now snag - Most of  
Blaze Rotted away possible scribe  
visible.

20" now 28" FIR N 29° W W, 19 ± ft  
2 live - shows very good scar -  
we do not open - Rescribe -

"T215 R10W 521 CS BT"

2<sup>d</sup> cor point in place of old mon,  
set 1" I.P. & BRASS CAP MKd

"COUNTY SURVEYORS OFFICE 1968  
T215 521 | 522 R10W" Deposit old  
COR. material along side BRASS CAP  
MARK new BT. -

20" D. FIR N, 57° E. 29<sup>3</sup> ft.

Mkd. "T215 R10W 522 CS BT"

This cor. lies approx 155 ft.  
E. of Top of Ridge course NE-SW,  
& The Record Dist. is 297 ft. E. of  
The cor. of sec. 27 & 28.

July 8, 1968

#27 W.A. Tracy C.S. URT 521 | 522 1-19  
T.H. J.W.B.