

1213

Renew Sec. Cor 55/54 T225R10W

Fd. 2" I.P. filled with concrete
& BRASS cap BROKEN off at cor.
with 1919 B.T.S as follows -

14" Now 32" Fir S. 75° E. 26 1/4 ft.

alive - shows good scar - we do not open
Rescribe "T225R10W 54 CS BT"

12" Now 20" Alder S. 31° W 39 1/2 ft.

alive - shows scar we Rescribe
"T225R10W 55 CS BT"

at cor. point in place of I.P. set
1" I.P. & BRASS cap MKD. "COUNTY

SURVEYORS OFFICE 1968 T215

55/54 T225 R10W" & Deposit old
pipe & BRASS cap on side. we used
O.B.T.S because new trees would be

too far. This cor. lies on
steep NW. slope 50 ft E. of
small ravine course N.E. & approx
220 ft west of top of spur sloping
N.E. dense salmonberry & vine maple
brush.

May 15, 1968

V.R.T.
J.H.
V.R.

[Signature]
#122-10

D.K. G.S. File No. 54/1-22