

Renew Sec. Cor. T215 535/536 T225 R10W

Fd. OBTs 25 Recorded in 1919
25 Follows -

14" Now 26" Fir N. 39° E. 25 1/2 ft.
Turned out & slid down hill

60" Now 65" Fir N. 53° W. 54 1/2 ft.
Now snag ^(50 ft high) - we open & find scribe.

No Trace of I.P. & Brass cap
set in 1919 - 2^d cor point set

1" I.P. & Brass cap MKd. "COUNTY
SURVEYORS OFFICE 1968

T215 535/536 T225 R10W" & MK.

New B.T.S. -

14" Maple N. 59° W. 47 1/2 ft.
MKd. "T215 R10W 535 CS BT"

16" D. Fir N. 11° E. 57 3/4 ft.
MKd. "T215 R10W 536 CS BT"

This cor. lies on E-W, cutting
line on very steep N.E. slope.

Note - Set 6 ft. steel fence post along
side Brass cap.

May 16, 1968

V.R. J.
V.P.

V.R. Tracy

#120

#38 T22-1D

C. S. File No. 57/1-23