

Revised $\frac{1}{4}$ S32 T22S T21S R10W

Fd. I.P. filled with concrete - Brass cap broken off & Fd. in Duff when excavating for new mon. Find as follows
1919 10" Now 16" Alder N. 35° E, 13 2/3 ft
Record 10 1/2 ft - 2 live - we open & find edge of 2x6 Blaze - Badly decayed. only hole where N.W. BT probably stood fits Record Bearing & Dist.

at cor. point in place of old pipe set 1" I.P. & Brass cap MKD. COUNTY SURVEYOR'S OFFICE 1968 T22S ~~T21S~~ ~~R10W~~ ^{R10W} & Deposit old cor. material alongside. MARK new BT's -

12" D. FIR N. 45° E 26 1/2 ft MKD. $\frac{1}{4}$ S32 CS BT"

7" D. FIR N. 11° W, 13 2/3 ft MKD. $\frac{1}{4}$ S32 CS BT"

This cor. lies on steep N.W. slope 50 ft. west of spur sloping N.W.

May 21, 1968

V.R.T.
J.H.
V.P.

(Handwritten signature)

#16
#41-122-10

C. S. File No. 54/1-29