

Renew N. $\frac{1}{4}$ $\frac{121-2}{55}$ T225 R10W

Fd. 1919 G.L.O. BRASS cap Buried & Broken
off CONCRETE I.P. in place & 1919 B.T.s
25 follows -

6" now 8" CHERRY S. 83° E. 15 $\frac{8}{8}$ FT.
DOWN & Decayed Laying across I.P. -
NO scribe fd.

9" now 18" ALDER S. 25° W. 16 $\frac{5}{8}$ FT.
Record S. 20° W,
2 live - shows SCAR - we do not open
Rescribe on BARK. " $\frac{1}{4}$ 55 CS BT"

2⁺ COR. point in place of old Pipe
set 1" I.P. & BRASS cap MKD. "COUNTY
SURVEYOR'S OFFICE 1968 T215
 $\frac{1}{4}$ 55 T225 R10W" & MK.

new B.T.s -

26" D. FIR S. 21° W. 39 $\frac{2}{2}$ FT.
MKD. " $\frac{1}{4}$ 55 CS BT"

14" D. FIR S. 42° W. 58 $\frac{5}{5}$ FT.
MKD. " $\frac{1}{4}$ 55 CS BT"

This COR. Lie 297 ft W. of
USFS. Line Tag on Top of Ridge
sloping N.W. Deposit old cor. material
along side BRASS cap.

May 23, 1968

WRT.
V.P.

#12/ R. Tray
#42-T22-10

C.S. File No. 54/1-30