

Renewal

25/30
36/31

T215 R 12-11 W

Found

ORICO.

30" D.F. 1/2 N. 36 E 59'

Found Bark Surveys "2" & other marks.

Possible cedar down in Draw.

No Trace of other BT's.

Renewal

Set Brass cap at sec. con. MKR
County Surveyors office

R	T 215	R
12	525	530
W	36	31

1971

New Bearing Trees:

6" Spruce N 55 W 36'
Sanded S 25 CS BT

22" P.F. North 32'
Sanded T 215 R 12 W S 25 CS BT

38" Spruce N 48 E 45'
Sanded T 215 R 11 W S 30 CS BT

No Trees to the south:

Note:
This cap lies approx 12' north
of Rarison Boundary E. W

#62-1116 W
#26-12W S.W. B.

2-9-71

C. S. File No. 54/1-457A

DIETZGEN NO. 3855-6

DEAR MRS. YATES:

THE COR. TO SEC'S.

R12W	R11W
25	30
36	31

FILED
 RECEIVED
 OCT 25 1976
 COUNTY SURVEYOR
 DOUGLAS COUNTY, OR

AS MONUMENTED BY YOUR OFFICE OF

2-9-71 MENTIONS A 38" SPRUCE B.T.

WH. BRS. N 48° E, 45.5' etc. THE

SPRUCE SHOULD BE A WHITE FIR.

THIS CAUSED ME CONSIDERABLE TIME

AND EFFORT DUE TO THE WRONG

DESCRIPTION FOR THE B.T. YOU'LL

PROBABLY WANT TO CHANGE YOUR

RECORDS ACCORDINGLY.

THANK YOU,

DICK HINTZ

C.S. 54/1-42

NOTED ON RENEWALS