

Renew Sec. Cor. T315 R7W  $\begin{array}{r|l} 517 & 516 \\ \hline 520 & 521 \end{array}$

Fd. one orig. BT at cor. 25 follows -

38" Now 42" Fir S. 25° W. 19  $\frac{1}{2}$  ft.

Shows "T35" old BARK scribe.

This BT now SN29 approx 60° high.

All other trees gone. Set 1" I.P.

& Brass Cap MKd. "COUNTY SURVEYOR'S

OFFICE 1965 T315 R7W  $\begin{array}{r|l} 517 & 516 \\ \hline 520 & 521 \end{array}$

CORNER point falls on 14" Log - we set

Brass cap under log. MK. New BTs -

14" D. Fir N. 10° W. 34° ft.

Mkd. "T315 R7W 517 CS BT"

26" D. Fir N. 70° E. 37  $\frac{6}{16}$  ft.

Mkd. "T315 R7W 516 CS BT"

24" D. Fir S. 33° E. 43  $\frac{6}{16}$  ft.

Mkd. "T315 R7W 521 CS BT"

26" D. Fir S. 46° W. 51  $\frac{2}{16}$  ft.

Mkd. "T315 R7W 520 CS BT"

This cor. lies in small Ravine

sloping N. 40° E.

April 16, 1965

V.R.T.  
M.D.  
J.B.

~~W.R. Tracy~~

0  
#47  
+\*