

Renew $\frac{1}{4}$ 58/59 T265 R3W -Ren. #3

Ed. 1924 G.L.O. BRASS CAP Bent
over & STUMP holes at PROPER
Bearings & Distances for BT's

Recorded in 1924 Resurvey. We
Reset BRASS CAP. Since the
Closest TREES are approx 600 TO
800 ft off, we use Most Southerly
Pole of 3 wire TRANSMISSION LINE
as Bearing Object as follows -

Pole BEARS N, 32° W, 199.5 ft
we put Yellow Line Tag on pole
Facing COR.

No evidence of Ren #3

Jan. 21, 1966

U.R.T.
M.S.
J.L.

R. J. May

FILED
RECEIVED

JAN 21 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#135

*

C.S. File No. 54/7-2