

525 | 530

Renew Sec. Cor. 536 | 531 T265 R's 2 & 3 W

Fd. one live BT at Cor. Location as follows

26" Now "D.F.I.R S. 45° E. 21 3/8 ft.

previously opened & shows Good "S" scribe

No Trace SW, BT & NE. BT possible Rotted

Log 134 in in approximate location - We set

1" I.P. & BRASS Cap MKd "COUNTY SURVEYOR'S

OFFICE 1966 T265 R3W 525 | 530 536 | 531 R2W"

& MARK new BT's -

6" D.F.I.R N. 61° E. 4 5/8 ft.

Mkd. "T265 R2W 530 CS BT"

6" D.F.I.R N. 5° W. 16 1/4 ft.

Mkd. "T265 R3W 525 CS BT"

7" D.F.I.R S. 37° W. 7 5/8 ft.

Mkd. "T265 R3W 536 CS BT"

We use ORIG. BT TO S.E.

Jan. 28, 1966

J.W.B.  
V.R.T.  
M.S.  
J.L.

FILED  
RECEIVED

JAN 28 1966

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

+ ~~13~~ R2-34

13-123

C. S. File No. 54/7-31