

Renew  $\frac{1}{4}$   $\frac{533}{54}$  T255 R3W T265

Fd. 1943 G.L.O. BRASS CAP FOR COR.

& Following. BTs -

ORIG. 42" D. FIR S. 85° E. 114<sup>2</sup> ft. (face)

previously opened - face pitched over.

12" Now 18" D. FIR N. 52<sup>3</sup>/<sub>4</sub>° W. 17<sup>8</sup> ft.

Shows very good scar - we do not open.

12" Now 14" D. FIR S. 10<sup>3</sup>/<sub>4</sub>° W. 10<sup>6</sup> ft.

Shows good scar - fence wire wrapped

around BT & grown over. These BTs

Mkd in 1943 by G.L.O. we mk. New

B.T. -

9" D. FIR S. 51° W. 22<sup>3</sup> ft.

Mkd. "  $\frac{1}{4}$  54 CS BT "

Feb. 18, 1966

U.R.T.

M.S.

J.H.

*(Handwritten signature/initials)*

FILED

RECEIVED

FEB 18 1966

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

#29-T25

\* #160-T26

C. S. File No. 54/7-39