

Renew Sec. Cor <sup>532/533 T255 R3W</sup> 55/54 T265

Fd. 1943 G.L.O. BRASS Cap at cor. MKd.

T255 R3W 532/533

55/54 T265 1943" 1 BT's as follows

orig. 50" Fir N. 25° E. 15 8 ft.

BRKscribed "T255 R3W 533 BT" - 2 live

only Rotted Remnants left of other orig. BT's

we find BT Recorded in Ren. # 13 of T255 R3W-

7" now 10" Yew N. 20° W. 17 8 ft.

2 live - scribe visible on partially healed face.

8" now 13" Yew N. 37 1/2° E. 35 6 ft.

2 live - scribe visible on partially healed face.

50" Fir (stump) S. 76° E. 48 3 ft.

scribe visible on face.

8" now 11" Yew S. 62° W. 9 9 ft.

2 live - scribe visible on partially healed face.

we MK. New BT -

18" W. Fir S. 22° E. 44 6 ft.

Mkd. "T265 R3W 54 CS BT"

BRASS cap lies in E.-W. fence 76 ft.

West of fence cor.

Feb 18, 1966

V. R.T.

M.S.

J.H.

440-T25  
\*461-T26

C. S. File No. 54/7-40