

Renew $\frac{1}{4}$ $\frac{517}{520}$ T265 R3W

Fd. old auto SPRING FOR COR. & BT's as Recorded
in Renewals # 44 & 67 as follows -

Orig. 20 "Now 28" B. Oak S. 3° E. 10° ft.

Scribe MKs nearly rotted away.

Ren. #44 BT-2 24" D FIR N. 69° W. 44° ft.

Scribe visible on unhealed Blaze - Now Stump.

Ren. #67 BT-2 10" Now 15" D. FIR N. 68° E. 23° ft.

Blazes healed. 2 live & good cond. we
do not open. also find $\frac{1}{2}$ " I. Bolt

Bent over - Ren. #44 - We set 1" I.P. & BRASS

cap MKd " COUNTY SURVEYORS OFFICE

1966 T265 $\frac{1}{4}$ $\frac{517}{520}$ R3W" & MK new BT.

8" D. FIR S. 88° W. 5 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ S 20 CS BT "

BRASS cap is set along side of
auto SPRING. COR. lies 34 ft
West of N.-S. fence,

March 7, 1966

V.R.T.
M.S.
J.H.

* 173

C. S. File No. 54/7-47